Zehnder ComfoWell Manifold


w/ twist-connect terminations


zehnde


CW-M 220 4-port manifold CW-M 320 6-port manifold CW-M 420 8-port manifold CW-M 520 10-port manifold CW-M 625 12-port manifold




Installer Manual














2019.09.17















2019.09.17

3



To cap an un-used port, install twist connector and push red plug all the way to the bottom past slots.

